

#2

Monica Sundarsh

Item 5: Section E

I live on 27th between Shower & Kaloli
all 4 of those speed bumps are different
& the 1st one coming off of Kaloli
is HORRIBLE!!! Too high.

~~If the size is going to be changed,
why were they put the rest put in
@ the incorrect sizing? Waste
of our money. All four installed
last Thursday between Shower &
Kaloli on 27th~~

Were the bumps that were installed ~~on~~
last Thursday following the new
measurements?

So we are stuck with what we have